

Recent Waterline and Sewer line activities in Tyrone Date: January 5, 2025



Broken water valve (curb stop) replacement on Chalcopyrite Court




Southwest Envioserv scoping the sewer lines

Recent Waterline and Sewer line activities in Tyrone Date: January 5, 2025



Recovered chimney sweep brush in sewer line during video scoping. BTW this doesn't belong in our wastewater lines

Recent Waterline and Sewer line activities in Tyrone Date: January 5, 2025



Main wastewater line on Copper Drive. Full of cobwebs that block the camera



Inside a typical manhole in Tyrone

Recent Waterline and Sewer line activities in Tyrone Date: January 5, 2025



Broken steel line inside sewer line An unknown homeowner or plumber lost this device and it ended up in our main wastewater lines

Recent Waterline and Sewer line activities in Tyrone Date: January 5, 2025



HEI clearing an obstructed line identified during the video scoping of the wastewater lines



Video Camera in sewer line